

Defects by Inspection Report

Client	flexidata	Work Order	33
Project	birmingham	Project Start	01/09/2004
Location	tyy	Start Tape	22
		UOM	Ft
		Setup	12
Database	C:\FLEX6\DATA\FLEX6DVS.MDB		Printed on
			09/08/2004

Setup	Manholes			Structural conditions								Service Conditions						Misc				
	From Manhole	To Manhole	Surveyed length	Break in pipe	Collapse	Cracks	Fracture	Deformation	Defective Joints	Defective Lining	Defective Taps	Roots	Grease	Encrustation & Scale	Settled Deposits	Infiltration	Obstruction	Line Deviations	Water Level +20%	Survey Abandoned	Camera Underwater	
1	NLAT	9040-085A	46.1																			
2	9040-029	9040-028	249.0																3			
3	9040-028	9040-027	398.0			10																
4	070A	30"	73.0																			
5	9040-004	9040-007	20.0																			
6	9039-296	9039-297	28.0								5						1			1		
7	9039-299	9039-298	323.0	3	1						10											
8	2772	2778	100.0	1	4									1								
9	2772	2778	12.0		1																	
10	2772	2778	12.0		1																	
11	2772	2778	0.0		1																	
12	2772	2778	0.0																			
Totals			1,261.1	4	0	18	0	0	0	0	0	15	0	0	1	0	0	1	3	1	0	