

# CCTV Defect Scores report for Structural defects

<b>Client</b> Garden Grove	<b>Project</b> flexiplayer example	<b>Location</b>	<b>Project Start</b> 06/14/2005
<b>Database</b> E:\FLEX6\DATA\GARDEN GROVE DEMO.MDB			<b>Printed on</b> 11/12/2008

Setup	PLR	Length	Defects	Pipe Rating	Quick Rating	Mean Pipe Score	Pipe Ratings Index	ICG
14	SPM130048	308.0	4	11	4131	0.00 Excellent	2.80 Good	2
18	MHM130049 9	80.0	4	8	2400	0.10 Excellent	0.00 Excellent	2
11	SPM130049	332.3	2	3	2111	0.00 Excellent	1.50 Excellent	2
15	SPM130048	308.0	1	2	2100	0.10 Excellent	2.00 Good	2
13	SPM130041	306.1	1	1	1100	0.00 Excellent	1.00 Excellent	1
17	MHL130016 X	133.0	0	0	0000	0.00 Excellent	0.00 Excellent	1
16	MHL130016 X	133.0	0	0	0000	0.00 Excellent	0.00 Excellent	1
12	SPM130040	306.0	0	0	0000	0.00 Excellent	0.00 Excellent	1
<b>Totals</b>		1,906.4	12	25				



**PipeLogix Inc.**  
**Phone: 866.299.3150**  
**Fax: 760.406.6023**