

# Grade Count report

Client <b>QC</b>	Work Order <b>4321</b>
Project <b>Project Title -1/2/2004</b>	Project Start <b>01/02/2004</b>
Location <b>Rancho Mirage</b>	Start Tape <b>123</b> UOM <b>Ft</b> Setups <b>4</b>
Database <b>C:\FLEX6\DATA\PACP.MDB</b>	Printed on <b>09/08/2004</b>

Setup	Manhole		Pipe			Grade count					
	From	To	Svy length	Diameter ins	Material	5	4	3	2	1	0
1	123456	654321	130.0	8	Polyvinly Chloride	2	0	4	2	2	9
2	1234	4321	50.0	6	Polyvinly Chloride	0	0	4	2	0	6
3	45678	87654	100.0	8	Brick	2	0	0	1	0	7
4	1234	4321	0.0	6	Polyvinly Chloride	0	0	0	0	0	3
Total surveyed length			280.0	Grade count totals		4	0	8	5	2	25