


Pipe Graphic Report of PLR MHM130049 9 for Garden Grove

Setup 18	Surveyor JMS	Certificate # U-105-538	System Owner		
Drainage		Survey Customer			
P/O #	Date 2004/03/19	Time 14:25	Street 9331 Central Ave		
Locality Garden Grove	Further location details				
Start MHM130049	Rim to invert	Grade to invert	Rim to grade	Ft	
Finish MHM130050	Rim to invert	Grade to invert	Rim to grade	Ft	
Use Sanitary	Direction Downstream	Flow control	Tape/Media # 026		
Shape Circular	Height 8	Width ins	Preclean J	Year Cleaned	
Material Reinforced Plastic Pipe (1 russ Pipe)	Joint length 3.0 Ft	Total length 80.0 Ft	Length Surveyed 80.00		
Lining	Year laid	Year rehabilitated	Weather Heavy Rain		
Purpose	Cat				
Additional info			Structural	O&M	Constructional
Location			Miscellaneous	Hydraulic	



PipeLogix Inc.
Phone: 866.299.3150
Fax: 760.406.6023